

PORT OF SILLOTH NOTICE TO MARINERS NO. 04/2016

SOLWAY FIRTH – Navigation Buoys

NOTICE IS HEREBY GIVEN THAT, the following Navigation buoys have been renewed and returned to their charted positions as shown on Admiralty Charts 1346 and 2013.

Notices to Mariners numbers 09/14, 05/15 and 03/16 are hereby cancelled.

Solway Buoy - FI G 4s

54°47.50" N 003° 30.00"W

Corner Buoy - FI (2) G 6s

54° 48.90"N 003° 30.00"W

Beckfoot Buoy - FI (3) G 10s

54° 50.30" N 003° 27.30"W

Capt. I Macpherson – Deputy Harbour Master - Silloth Docks

4th October 2016

www.abports.co.uk/Marine/Short_Sea_Ports/Silloth/

Current 'In Force' Notices to Mariners:

04/2013 - Boarding and Landing of Pilots

10/2014 - Navigation Waypoints

01/2015 - Silloth Sewage Outfall Beacon – Light Extinguished

04/2015 - Change to Inbound VHF reporting procedures

01/2016 - Wooden Dolphin & lights re-established

02/2016 - Maximum Draft Calculation

04/2016 – Navigation Buoys